



Amer-Plate Sheet
Section A-A

Ameron PROTECTIVE LINING DIVISION

REPAIR DETAIL FOR SMALL
HOLE IN T-LOCK LINING

DRAWN P.K. 8-86
APPV'D

PLD-TL-104C

REV
A