



Amer-Plate Sheet Typ.



Section B-B

Ameron PROTECTIVE LINING DIVISION

REPAIR DETAIL FOR LARGE
HOLE IN T-LOCK

DRAWN P.K. 8-86
APPV'D

PLD-TL-104D

REV
A