

REPAIRED
STRUCTURE

EMBEDDED METAL
ANGLE


1" SAW CUT

SEALANT RECOMMENDED
BY LINER MANUFACTURER

2X2 ANGLE STRIP
CUT TO 3/4" ONE
SIDE

1" WELD STRIP

EXISTING T-LOCK LINER



Amerpon PROTECTIVE LINING DIVISION

T-LOCK TERMINATION DETAIL AT
REPAIRED EMBEDDED ANGLE

DRAWN	JPG	4/08
APPV'D	JP	4/08

PLD-TL-510

REV
0